

153476

CERRO COPPER PRODUCTS CO.

INTERNAL MEMORANDUM

Other Addressees

P. Tandler
R. E. Conreaux
J. Burroughs
J. Hintz
J. Davis
File

1104

To: M. McNerney

Date: August 17, 1990

From: J. M. Grana

Subject: Sewer Emergency

The cross-connection between the two east-west sewer lines on either side of the main plant road is plugged with sandbags in the manhole shown on the attached map. The sandbags have a rope attached to them and can be used to pull the plug.

The sandbags should only be pulled when the sewers in the plant that flow to the East Outfall require relief because of flooding. The attached map shows the area of potential flooding. The decision to pull the plug should be made by a supervisor familiar with the situation. However if a flooding situation appears likely but has not occurred, the supervisor should contact those individuals in the order shown below for prior approval.


Whenever the sandbags are pulled a written report to my department should be submitted the following day.

---Joe Grana
---Joe Burroughs
---Mike McNerney
---Jim Hintz
---Paul Tandler
---Bob Conreaux

Joe

C03677

Sewer plugged



MONITORING LOCATION

C03678

CERRO COPPER PRODUCTS CO.

A member of The Marmon Group of companies

INTERNAL MEMORANDUM

HQ-10

SHOW NAME, TITLE AND UNIT OF ADDRESSEE AND ADDRESSOR

OTHER ADDRESSEES - FOR INFORMATION

M. McNerney cc: P. Tandler
J. Miller
P. Plummer
R. Thompson
R. Faries
J. Davis
E. Perschbacher
J. Hintz

File

1104

TO: Distribution

DATE: August 13, 1990

FROM: R. E. Conreaux

SUBJECT: OIL LOSSES TO THE SEWER

Paul Tandler has indicated that we had unusually high charges from the Treatment Plant for June and July for oil and grease removal. Prior to June our costs were running very low.

We know that part of the July cost was due to cleaning the trough and concrete tank, but cannot account for the rest.

Please check to see that all equipment is functioning properly.



REC/jpl

C03679